

Application No.: 10/811,876

AMENDMENT TO THE DRAWINGS

Please amend Fig.'s 1, 17 and 18 as indicated in the attached Replacement Sheets.

With respect to Figure 1:

The "4:SOURCE SIGNAL LINE" will now read 5:SOURCE SIGNAL LINE.

The "5:GATE SIGNAL LINE" will now read 4:GATE SIGNAL LINE.

Figures 17 and 18 have been labeled "Prior Art"

BEST AVAILABLE COPY

REPLACEMENT SHEET

1 / 18




FIG. 1

REPLACEMENT SHEET

17 / 18




FIG. 17

(Prior Art)

REPLACEMENT SHEET

18 / 18

(K-K')




FIG. 18a (Prior Art)

(L-L')




FIG. 18b
(Prior Art)

(M-M')




FIG. 18c

(Prior Art)

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.